



For a full detailed engineering report on the station, click here:
<http://www.ctrailgovernance.com/reports/Darien.pdf>



Indoor lights (used outdoors) fill with water when it rains, short circuiting all platform lights causing a blackout.



Platform crumbling from beneath – several locations, both sides.



Trash on the tracks under bridge plates.



Old rusty (and unused?) paper boxes clog platforms.

Photos by JIM CAMERON

7/4/06