



For a full detailed engineering report on the station, click here:  
<http://www.ct.gov/dotinfo/cwp/view.asp?a=2183&Q=295632&dotinfoNav>



**Exposed electrical wiring.**



**Cracked concrete.**



**Repaired, but broken again. Steps to Hollow Tree Ridge Rd.**



**More deterioration on steps to Hollow Tree Ridge Rd. at SW corner of station.**



**Platform siding bowed outward.**



**Platform crumbling from beneath.**



**More “divots” in the concrete.**

**Photos by JIM CAMERON**

**7/4/06**