



For a detailed engineering report on this station, click on the link below:

<http://www.ct.gov/dotinfo/cwp/view.asp?a=2183&Q=295632&dotinfoNav>



Rusted underside of the canopy.



Defaced signs and graffiti



Graffiti seen from inside the waiting area



More graffiti



Artwork... or graffiti?



Definitely not art work.

:Photos by BEN HECKSCHER, JR.

July 19, 2006