



<http://www.ct.gov/dotinfo/cwp/view.asp?a=2183&Q=295632&dotinfoNav>



Insufficient bike racks.



Trash under the platform.



Junk under the platform.



Concrete in need of repair.

:Photos by BEN HECKSCHER, JR.

July 19, 2006