


Selector Switch Parts for Bryant Zinc/RRS/WRRS AutoFlag #5



Remanufactured by
:
Continental Contacts
1832 Mearns Rd
Warminster, PA 18974

Phone: (215) 443-0558
Fax: (215) 442-0288

Email: JohnMajewski
(ccsi@prodigy.net)

Index Number	Part Number	Description	Price
A	T-720	Contact with Round Tip	\$47.25
B	T-721	Brass Finger Guides (2 of them)	\$16.20
C	T-722	Contact Finger with Tip	\$47.25
D	T-723	Support Post	\$45.00
E	I-186	Nylon Pin	\$13.00
F	T-724	Base Support	\$48.60
G	J-263	Electrical Shunt	\$5.00
A-F	T-725	Complete Assembly	\$222.30
H	T-715	Contact Buttons (each)	\$15.00

These parts were redesigned so that the parts that wear can be replaced like Index Numbers A, C, F and H. In order to use this functionality, you will need to purchase the appropriate parts to hold them as the originals did not allow replacement. Index Numbers H and C will fit on an existing unit without any modification.

Note that this is for a standard selector switch that was most commonly used - several varieties of selector switches were made such as a pole-changing relay variety and a few other styles. Contact John to see if your special ones can be remanufactured. Continental Contacts will also do custom work on other types of contacts and small metal parts. Contact John for a quote.