



For a full engineering report on this station, click here:

<http://www.ct.gov/dotinfo/cwp/view.asp?a=2183&Q=295632&dotinfoNav>



Less than a decade after its multi-million dollar rehabilitation, the New Canaan station has already suffered damage from buses colliding into the platform roof.



Another look at the damage to the New Canaan station roof. Buses are used instead of trains on the branch line several times each month.



New Canaan station is the "end of the line". But why can't the trash be picked up?



Talmadge Hill Station: Seems to be a collecting point for unwanted trash underneath the platform.



Talmadge Hill Station: No secure station, just a wind shelter and a soda machine eating up valuable platform space.

Photo's submitted July 11, 2006 by GEORGE MARANIS, Administrative Officer, Town of New Canaan.