



For a full engineering report on this station, click below:

<http://www.ctrailgovernance.com/reports/Cos%20Cob.pdf>



Broken railing and grafitti.



Garbage and debris under platform.



More graffiti in the waiting room.



Why do newspaper boxes hog valuable real estate on the platform, blocking the stairs?



People love to ride their bike to the station, but there aren't enough racks for riders to store their bikes securely.

:Photos by BEN HECKSCHER JR., July 19, 2006