




For a full engineering report on this station, click here:

<http://www.ctrailgovernance.com/reports/Fairfield.pdf>



Rust and decay on the overhead canopy



How many people does it take to screw in a light bulb?



Loose, dangling wires



Warning stripe at the edge of the platform is worn away.

Photos by JEFF STEELE

July 12, 2006