



For a full engineering report on this station, click here:

<http://www.ct.gov/dotinfo/cwp/view.asp?a=2183&Q=295632&dotinfoNav>



“A Tree Grows In Stamford”... right over the signs, but not the parking meters: \$3 per day or up to \$84 per month!



Bus shelter wall is missing. Only half a bench available.



Parking pavement is cracked and filled.



**Not artwork. Not a mural.
This is grafitti.**



**The fence has collapsed
providing no protection from
the tracks.**



**No maintenance. Fence falling
down and weeds run wild.**



**What is this sign telling us?
Nothing!**



Broken stone wall.

Photos by Amy Lamborn

July 26 2006





Photos by MARILYN TREFRY 8/4/06